

Martin Diesel Service Ltd

237 PTH 52W, Steinbach, MB R5G 2S9
Phone: (204)326-2408 ~ Fax: (204)326-1693
Toll Free 1-888-882-9399
Email:info@martindiesel.net
GST #R103544656

Invoice

Bill To RM of Ste. Anne (EMAIL x2)
Box 6 Grp 50 RR1
395 Traverse Road
Ste. Anne, MB R5H 1R1
Canada

Business (204) 422-5929
Chris-Fire Chief +1 (204) 381-0057
Invoices info@rmofsteanne.com

Invoice # 215041
Work Order # 260409
Service Advisor Clint Wiens
Technician Martin Diesel

Plate MB CKF703
Description 2012 Freightliner M2 Business Class
ISC-73300554
VIN 1FVHCYBSXCHBN4400
Unit Tanker #47 - Richer Fire
Odometer 357,077

Invoice Date 11/21/2025 8:05 AM
Appointment 11/20/2025 8:17 AM
Promised 11/20/2025 8:17 AM

Service

Gov't Safety Inspection - Hvy Truck

10-SAFETY DECAL - MANITOBA GOV'T
Labour: A-Inspection (C026304)

1 Unit	\$5.00 / Unit	\$5.00 G
		\$250.00 *G
	Sub	\$255.00

Safety repairs

Repairs required to complete safety

Safety repairs: Inspect and measure all brake components.
Adjust all brakes, replace slack adjuster lock pawls on the
right front drive and left rear drive. Protect air lines from
rubbing on air dryer. Hook up service tool, check and clear
codes. Had inactive TPS codes, customer to monitor.

\$248.90 *GP

04-R801700 - AUTO SLACK PAWL LOCK

2 Unit	\$26.10 / Unit	\$52.20 GP
--------	----------------	------------

10-83-6029 - CABLE TIE 15 "

2 Unit	\$0.23 / Unit	\$0.46 GP
--------	---------------	-----------

22-L57224 - RAD HOSE 1 1/2 "

6 Unit	\$1.81 / Unit	\$10.86 GP
--------	---------------	------------

Sub		\$312.42
------------	--	-----------------

COMPLETE SERVICE

CHANGE OIL & FILTERS, LUBE CHASSIS & CHECK ALL FLUID LEVELS.

Labour

\$130.00 *GP

19-03-43845-000 - FUEL FILTER

1 Unit	\$36.72 / Unit	\$36.72 GP
--------	----------------	------------

19-FF5636 - FILTER , FUEL

1 Unit	\$32.22 / Unit	\$32.22 GP
--------	----------------	------------

19-LF9009 - OIL FILTER (EHC 1.00)

1 Unit	\$58.25 / Unit	\$58.25 GP
--------	----------------	------------

21-SHELL ROTELLA T - 15W40 ENGINE OIL (incl EHC of
.05)

18 Unit	\$6.28 / Unit	\$113.04 GP
---------	---------------	-------------

Sub		\$370.23
------------	--	-----------------

Service Air Dryer

Labor: Remove and replace air dryer cartridge.

\$39.30 *GP

04-R950011 - CARTRIDGE,AIR DRYER..SPIN ON

1 Unit	\$44.04 / Unit	\$44.04 GP
--------	----------------	------------

Sub		\$83.34
------------	--	----------------

Total Parts

\$352.79

RE-TORQUE WHEELS AND U-BOLTS WITHIN 100KM. THIS IS CUSTOMER'S RESPONSIBILITY.

Modifications to emissions or horsepower may void warranties.

Return/Refund Policy: Please provide this invoice number when returning any product for a refund request. Returns will be accepted up to 30 days from invoice date in their original packaging and please note that all returned items are subject to a restocking fee. Special order and electrical parts may not be acceptable for return due to original manufacturers guidelines.

Total Labor		\$668.20
Total Before Taxes & Miscellaneous Charges		\$1,020.99
(*) Shop Supplies		\$43.43 GP
(G) Canadian Goods and Services Tax (GST)	5 %	\$53.22
(P) Manitoba Provincial Sales Tax (PST)	7 %	\$56.66
Grand Total		\$1,174.30

RM of Ste. Anne (EMAIL x2) charged \$1,174.30 to Account - RM of Ste. Anne (EMAIL x2) - Net 30 Days

I acknowledge my indebtedness to Martin Diesel Service Ltd for the amount of \$_____, for the work listed above, which has been completed on my authorization.

I further acknowledge that Martin Diesel Service intends to rely on the rights of a lienholder under the Garage Keepers Act.

Signature: _____

Name: _____

RE-TORQUE WHEELS AND U-BOLTS WITHIN 100KM. THIS IS CUSTOMER'S RESPONSIBILITY.

Modifications to emissions or horsepower may void warranties.

Return/Refund Policy: Please provide this invoice number when returning any product for a refund request. Returns will be accepted up to 30 days from invoice date in their original packaging and please note that all returned items are subject to a restocking fee. Special order and electrical parts may not be acceptable for return due to original manufacturers guidelines.